


Hardware

- SOC: [MT7622](#)
- Switch:
 - Realtek RTL8367S (<v1.0)
 - Mediatek MT7531 (>=v1.0)
- Wifi: bgn on SOC, MT7615-AC (was dropped due to heat)



From:
<https://wiki.fw-web.de/> - FW-Web - Wiki

Permanent link:
<https://wiki.fw-web.de/doku.php?id=bpi-r64:hardware>

Last update: **2019/10/29 13:16**

