

wifi

internal wifi

mt7622-wifi: works on my repo (5.4-main), but not in pcie-branch.

Needs softdep

```
cat /etc/modprobe.d/wifi.conf
softdep rfkil pre: mt7622
```

<http://forum.banana-pi.org/t/bpi-r64-mt7622-mac80211-wifi-driver/10246/27>

ath10k

needs firmware-package (apt install firmware-atheros)

and this in /etc/modprobe.d/local.conf:

```
options ath10k_core debug_mask=0xffffffff
options ath10k_core skip_otp=1
options ath10k_pci irq_mode=1
```

From:

<http://fw-web.de/dokuwiki/> - **FW-Web - Wiki**

Permanent link:

<http://fw-web.de/dokuwiki/doku.php?id=en:bpi-r64:wifi>

Last update: **2020/05/10 18:41**

